





1. Two-story residence with two one-story wings and two towers, all with stucco over brick on limestone foundation.




2. Clerestory tower topped by a pyramidal roof surmounted by iron finial.



3. Decorative wooden, diagonally positioned blocks surrounding north tower, south tower and the second story bay on north façade.




4. Multi-pane and small box windows throughout.



5. Metal acroteria on corners of south tower, north bay, and north entrance foyer.



6. Decorative chimney pots.



7. North tower with melon-shaped dome and crescent-shaped iron finial.




8. Inset woodwork of overlapping rounded arch design applied to the north façade.



9. Three rounded arch windows behind wooden support brackets on the north façade.




10. Rounded arch windows on three sides of the north tower.




11. Single-story service entrance on northeast topped by a melon-shaped metal dome.




12. Wooden bracing and decorative wooden brackets supporting second-story bay on north façade.




13. Entry porch on southeast corner with concrete balustrade and quatrefoil inserts.




14. Three keystone-shaped windows, two on south façade and one on east façade.




15. East main entry vestibule includes melon-shaped dome, triple south arched windows, , and multifoil horseshoe arch with inset door and transom. Also visible is a horseshoe arch with inset window on the east façade of the south wing.




16. "Villa Kathrine 1900" inset etching on east façade.




17. Inset decorative wooden frieze with pointed arch design on east façade.




18. Six vertical slots in north façade of service entrance over a single horizontal rectangular window.




19. South tower topped by a striped "minaret" with conical roof surmounted with a metal finial.




20. Inset diamond-patterned latticework resting on short pilasters on three sides of the south tower.




21. Narrow wooden frieze of stepped pointed arch design surrounding south tower.




22. Diamond-shaped, amber-colored glass windows inset in decorative frieze on three sides of south wing.



23. Syrian arch with inset window fronted by original decorative iron balustrade on the south tower.



24. Bay window on second level of south façade between south tower and main unit with ornamental brackets supporting soffit.



25. Bay window facing southwest with ornamental brackets supporting soffit.



26. Porch on northwest with stucco piers and decorative iron balustrades.




27. Double horseshoe arch with center wooden column and flanked by two engaged wooden columns on second level of the west façade.



28. Wooden louvered vents at foundation level.



29. Decorative painted design in horizontal strips containing a progressive series of triangles on north, east and west facades.



30. Stucco pillars with latticework privacy fence at the service entrance.



31. Replica of original flagpole on north wall of south tower.

