

CONTINUATION SHEET NO. ___

PROPERTY NAME _____
LOCATION 1466 VERMONT. CITY/TOWN/VIC _____
STATE _____ ZIP _____

HOUSE HAS EAST WING UNDER EXTENSION OF ROOF, VERY SHALLOW, TO ACCOMMODATE LANDINGS OF STAIRWAY TO 2ND FLOOR AND ENTRY. INTERIOR BUTTERNUT WOODWORK IS EASTLAKE CARVED AND IS IN NEW CONDITION. EXTERIOR BANDS OF DARKER RED BRICK SURROUND HOUSE AT TOP OF 1ST FLOOR, MID SECOND FLOOR AND IN GABLE AT TOP OF SECOND FLOOR. A VERY INTACT ORIGINAL HOUSE. ONLY CORBELLED ORIGINAL CHIMNEY HAS BEEN LOWERED AND IS NO LONGER ORNAMENTED.