

930 Kentucky

According to records, this American Craftsman Bungalow was built in 1914. The brick structure was built with a variation from your typical bungalow floor plan on an ashlar limestone foundation. The front gable features half timbered trim, simple eave brackets, and a triple window.

Take note of the mixed materials that are present on the front porch. Painted wood corbels with a small floral motif, wainscot ceiling, leaded glass window sections, and oak panels in the sidelights. The entry has plenty of light sources from the sidelights, transom light, and the east window. Notice the wood treatment at the front door and sidelight - oak was used on the side facing the porch and pine was used on the reverse side in the entry.

A double arched hallway takes you to the dining room with a bay window to the east. The front parlor's fireplace elements include green tiles, a beveled glass mirror, and a decorative iron fireplace covering. The second parlor's fireplace boasts oak and fluted columns.

The kitchen is still complimented by the original chair rail, pine trim, and cedar floor. To the south of the kitchen, a butler's pantry with painted paneled cupboards and bin drawer pulls, occupies a narrow but efficient space. Also to the south of the kitchen, an enclosed porch neatly follows with a painted brick wall and painted wood floor.