

Exterior Features to be Protected by Ordinance **
819 N. Fifth Street

1. Front facade.
2. Main entrance, overhang, roof, and brackets with carvings.
3. Front and side porches with their porch rails, floors and steps, plus porch paneling (reproduction).
4. First floor rectangular windows and doors, with their ^{SAW}dog-toothed limestone hoods with central carvings.
5. Cornice bracketing.
6. The gabled ends of all second-story dormers with centralized rosettes.
7. The four attic dormers, which are differently decorated with wooden stick-style gabled end camouflaging the typical ^{SAW}dog-toothed head and rosette behind.
8. South side bay window.
9. Quincy Preservation Commission gives permission that the flared-top front chimney (now removed) may be restored to its original design.
10. Three rear chimneys.
11. Stone foundation surrounding the house.
12. Exterior brick surface of house.

**Per meeting on 11/26/90 between Landmark Committee of Quincy Preservation Commission and David Smith.